
City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls	Company: Savin	Date: <u>10/15/2009</u>
Test to be performed:  Smoke Dyed Water X	Ground Condition.	
Manhole_ID: S05KK1001MH	Test ID: <u>D1032-034047</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Manhole	SO5KK1001MH
0			Start of Survey	
0			Water Level	
33.40000153			Dye Test Not Visible	
33.40000153			Abandoned Survey	DYE TEST IS COMPLETE